1/18




FIG.2A
PRIOR ART




FIG.2B PRIOR ART




FIG.3A
PRIOR ART





FIG.3B PRIOR ART



4/18




FIG.4B
PRIOR ART




FIG.5A PRIOR ART




FIG.5B PRIOR ART




FIG.5C PRIOR ART




FIG.6
PRIOR ART




FIG.7
PRIOR ART





FIG.8

<u>10</u>



## FIG.9A





FIG.9B

MEASUREMENT POINT	неі днт [ µ m]	MEASUREMENT POINT	не:GHT [ $\mu$ m]
1	132	12	121
2	128	<b>①</b>	126
3	122	<b>1</b> 5	125
5	133	`	**************************************
6	125	***************************************	
8	129		
10	127		311555555555555555555555555555555555555

# FIG.10

<u>20</u>



11/18

FIG.11A





FIG.11B

MEASUREMENT POINT	неі <b></b> GHT [ $\mu$ m]	MEASUREMENT POINT	HEIGHT [ # M]
1	128	(3)	127
2	121	1	125
(5)	134	(15)	123
6	124	<b>1</b> 6	112
<b>Ø</b>	131	<b>(19</b> )	121
8	138	<b>20</b>	126
10	122	Α	110
12	122		

# **FIG.12**


1

<u>3 0</u>




### **FIG.13**

<u>40</u>



## **FIG.14**

<u>50</u>



15/18

FIG.15A





FIG.15B

MEASUREMENT POINT	неі <b>с</b> нт [ $\mu$ m]	MEASUREMENT POINT	HEIGHT [ $\mu$ m]
1	131	13	136
2	125	10	123
3	124	<b>(</b>	129 .
4	130	16	131
<b>⑤</b>	123	1	129
8	130	<b>2</b> 0	119
9	118	A	128
12	128	B	122

## **FIG.16**

<u>60</u>



17/18

FIG.17A




FIG.17B

MEASUREMENT POINT	HEIGHT [ $\mu$ m]	MEASUREMENT POINT	<b>не</b> іднт [ <b>μ</b> m]
1	133	Α	131
2	124	D	126
3	133	F	130
4	125	Н	131
<b>⑤</b>	130		126
6	133	M	127
10	133	N	127
12	122	Р	118
<b>①</b>	115	S	121
18)	117	Τ	126

## **FIG.18**

